



Inspection Report

Inspection Date: 2017/09/12

Excavators

General Information

Maker	KUBOTA		
Model Number	U-30-3S		
Year	2006		
Hour (h)	-	Meter	Replaced
Serial Number	61643		

Options


- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		430		

Note for External Appearance

Not original color



Undercarriage


Shoe Type	Rubber	
Swing Circle	No confirmation of movement	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

The rubber shoes have deteriorated over time and are worn




Engine

Model	D1503
Serial Number	06Q0510
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component

- The hour meter has been replaced (1804h+1605h)
- The seat is partly torn



Note for Engine



Admin No. 2017090029