

FS165T Crusher/Recycler/Screen

2020/01/14

BASIC INFORMATION

Inspection Date		Model	FS165T	Serial No.	5018
Date of Manufacture		Hourmeter	99999 HR	Condition of Hourmeter	HR is broken
Hourmeter (Estimated)		Engine No.		Job Status	Other
Accident History		Type of Shoe	Grouser	Stamp	Not confirmed
Others					

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Traveling	Normal
Clutch		Crusher/Screen	Normal	Conveyor Device	Normal
Feeder		Console	Normal	Remote Control	

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	Yes (Right), Yes (Left)	Wear: Track Link Extension (Right)	Moderate/Within Service Limit	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread (Right)	Slight	Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins (Right)	Slight
Wear: Track Link Pins (Left)	Slight	Wear: Track Shoe/Rubber Shoe	Slight	Bent/Broken/Missing: Track Shoe	No
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Wear/Deformation: Tooth/Cutters	Wear: Moderate/Within Service Limit, Deformation: Moderate	Wear/Deformation: Screen	Wear: Moderate/Within Service Limit, Deformation: Moderate	Wear/Deformation: Jaw Crusher	
Crusher V belt		Wear/Deformation: Conveyor	Deformation: Moderate, Wear: Moderate/Within Service Limit	Wear: King Pins	

OIL/WATER/AIR LEAK

Aux. Cylinder (Right)	Slight Film ロットサビあり	Aux. Cylinder (Left)	Slight Film ロットサビあり	Oil Leak: Engine	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	
Oil Leak: Center Joint		Oil Leak: Crusher Device		Oil Leak: Conveyor Motor	No
Oil Leak: Crushing Motor		Oil Leak: Pump Device	No		

APPEARANCE

Main frame	Rusted/Corroded	Track Frame	Rusted/Corroded	Hopper	Rusted/Corroded
Side Covers	Deformed/Dent, Rusted/Corroded				

INTERIOR

Console	Malfunction モニター表示不良				
---------	-------------------------	--	--	--	--

OVERALL RATING

Appearance Evaluation	Fair	Rust/Corrosion	Heavy	Overall Rating	Able to Use
Special Notes	<ul style="list-style-type: none"> ・モニター表示不良 ・各シリンダーロットサビ、傷あり 				