



Inspection Report

Inspection Date: 2024/04/29

Excavators

General Information

Maker	YANMAR		
Model Number	B3-6A		
Year	2011		
Hour (h)	3864	Meter	Working
Serial Number	62881B		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	420			

Note for External Appearance

- Repainted



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	NG	NG
Sprocket	NG	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The crane fuck pine is missing
- Oil oozing from the bottom
- Concrete adheres to the bucket



Note for Undercarriage

- Oil oozing from the right travel motor



Engine

Model	
Serial Number	90952
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn
- The crane monitor is unable to read due to deterioration



Note for Engine



Admin No. 3000062326