



Inspection Report

Inspection Date: 2018/06/15


Excavators

General Information			
Maker	YANMAR		
Model Number	VIO70-3A		
Year	2011		
Hour (h)	1868	Meter	Not Working
Serial Number	36004B		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Breaker Piping


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	N/A	Unchecked	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)		630		

Note for External Appearance
- This item has a history of rollover accident
- The cabin and side covers are broken




Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The upper structure is for sale but detached




Note for Undercarriage




Engine	
Model	4TNV98-ZWBV
Serial Number	F0523
Engine Oil Leak	Oil oozing
Engine Oil Gauge	Not enough cooling water
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine
Oil leak in the engine room



Admin No. 2018061091