



Inspection Report


Inspection Date: 2018/03/14

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK115SR-1ES		
Year	2007		
Hour (h)	4321	Meter	Working
Serial Number	YV04-03929		

Options	
- CAB	- Air conditioner
- Multilever	- Breaker Pippings
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		840		


Note for External Appearance
Repainted


Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The arm is reinforced


Engine	
Model	BB-4BG1TRY-01
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Undercarriage
The shoes are loose


Note for Operating Component
- The seat is partly worn/torn
- The air conditioner is broken


Note for Engine


Lot No ARA013-0018 Admin No. 2018010705