



# Inspection Report

Inspection Date: 2023/03/02

## Truck

### General Information

<b>Maker</b>	ISUZU
<b>Model Number</b>	PB-FRR35K3S
<b>Year</b>	2004
<b>Mileage (km)</b>	188565
<b>Serial Number</b>	FRR35K3S-7003551

### Note for External Appearance

### Engine

<b>Model</b>	6HL1
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	Unchecked
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

### Note for Engine

- F6

Admin. No. 3000046700

\*This report is only for your reference. We are not responsible for the actual condition of checked item.