



Inspection Report

Inspection Date: 2018/06/15


Excavators

General Information			
Maker	YANMAR		
Model Number	Vio20-3		
Year	2006		
Hour (h)	3891	Meter	Working
Serial Number	32912B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		420		

Note for External Appearance
- The rear cover does not have a key cylinder
- The cover have some dents




Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage
The rubber shoes have deteriorated over time and are partly worn




Engine	
Model	3TNV76-P
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
- The seat is partly torn
- The backrest is detached



Note for Engine
Oil oozing from the oil cap



Admin No. 2018060924