



Inspection Report

Inspection Date: 2024/06/14

Excavators

General Information

Maker	KUBOTA		
Model Number	U40-6		
Year	2012		
Hour (h)	2943	Meter	Working
Serial Number	11389		

Options


- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)	545			

Note for External Appearance

- The body has some scratches and rust




Undercarriage

Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	NG	NG	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

- The I-link is detached
 - The bucket pin retainer is missing
 - The boom light is missing
 - The engine hood is distorted



Note for Undercarriage

- The sprockets are worn



Engine

Model	V2607-D1-E07
Serial Number	8CL4842
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Rust/Oil
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak


Note for Operating Component

- The seat is torn



Note for Engine

- The starter motor is broken



Admin No. 3000059318