



Inspection Report

Inspection Date: 2024/05/31

Excavators

General Information

Maker	KUBOTA		
Model Number	U-40-6		
Year	2014		
Hour (h)	4312	Meter	Working
Serial Number	13482		

Options

- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	545			

Note for External Appearance

- The paint is peeling off



Undercarriage

Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

- Oil leaks from the left travel motor



Engine

Model	V2607
Serial Number	3ES1653
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000059214