



Inspection Report

Inspection Date: 2026/01/16

Excavators

General Information

Maker	KOMATSU		
Model Number	PC18MR-2		
Year	2007		
Hour (h)	3380	Meter	Working
Serial Number	18243		

Options


- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	No	No	
Arm		Oil leak	No	Small
Bucket		No	No	Big
Bucket Size (mm)	390			

Note for External Appearance

- Repainted
- The body has some scratches and rust



Undercarriage


Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The width between the shoes is adjustable



Engine


Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component



Note for Engine

- The belt makes noise when accelerating at high speed



Admin No. 3000079737