



Inspection Report

Inspection Date: 2024/07/26

Wheel Loader

General Information

Maker	KUBOTA
Model Number	R430Z
Year	2011
Hour (h)	1022
Serial Number	R430-20605

Note for External Appearance

- Repainted



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

- The hour meter has been replaced
- The seat is torn



Engine

Model	D1703
Serial Number	AY0894
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 3000061647

*This report is only for your reference. We are not responsible for the actual condition of checked item.