



Inspection Report

Inspection Date: 2019/05/16


Excavators

General Information			
Maker	KOBELCO		
Model Number	SK75UR-3		
Year	1999		
Hour (h)	4701	Meter	Working
Serial Number	YR-04218		

Options	
- CAB	- Speed changer
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	No
	Right	N/A	N/A	
Arm		Oil oozing	No	Small
Bucket		Oil leak	No	Big
Bucket Size (mm)		680		

Note for External Appearance
- The lower parts of the frames have some dents
- The blade has some dents




Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The bucket is worn and has some holes




Note for Undercarriage
- The upper part of the blade is deformed
- Rusty



Engine	
Model	A-4JB1PYA-03
Serial Number	4JB1-171046
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component
- The seat has been fixed with sticky tape
- The monitor is not working



Note for Engine



Admin No. 2019050430