



# Inspection Report

Inspection Date: 2018/02/27

## Truck

### General Information

<b>Maker</b>	ISUZU
<b>Model Number</b>	ADG-FRR90K3S
<b>Year</b>	2006
<b>Mileage (km)</b>	61208
<b>Serial Number</b>	FRR90K3S-7001855

### Note for External Appearance

- Tire size: 225/90R17.5
- Crane model: URU374
- Crane maker: FURUKAWA
- Radio control

### Engine

<b>Model</b>	4HK1
<b>Engine Serial Number</b>	
<b>Engine Oil Leak</b>	No
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

- The airbag check light comes on
- F6

### Note for Engine

Engine power: 190PS

Lot No ARA013-0058

Admin. No. 2018020540

\*This report is only for your reference. We are not responsible for the actual condition of checked item.