



Inspection Report


Inspection Date: 2018/06/14

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO17		
Year	2007		
Hour (h)	2219	Meter	Working
Serial Number	00565B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pippings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		420		


Note for External Appearance
Repainted



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
The rubber shoes have deteriorated over time, are worn, and partly cracked


Engine	
Model	3TNV70-XBV
Serial Number	25476
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine
- The gasket of the engine head needs to be replaced according to the seller
- The water temperature check lamp is turned on


Admin No. 2018060859