



Inspection Report

Inspection Date: 2018/12/11

Excavators

General Information

Maker	YANMAR		
Model Number	Vio30-5B		
Year	2011		
Hour (h)	3311	Meter	Working
Serial Number	54662B		

Options

- CNP	
- Multilever	
- Blade	- Breaker Pipings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	470			

Note for External Appearance

The canopy is partly damaged and cracked



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

Oil oozing from the reduction drive of the right travel motor



Engine

Model	3TNV82A-N
Serial Number	87855
Engine Oil Leak	No oil leak
Engine Oil Gauge	Unchecked
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2018120022