



# Inspection Report

Inspection Date: 2024/08/13

## Wheel Loader

### General Information

Maker	CAT
Model Number	901B
Year	2006
Hour (h)	2901
Serial Number	CAT0901BVW7A01775

### Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

### Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

### Engine

Model	K3M-E4DT
Serial Number	K3M-30822
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Documents

Automobile Inspection Certificate	No
-----------------------------------	----

### Note for External Appearance

- Repainted



### Note for Upper Structure



### Note for Operating Component

- With CAB (cabin) heater  
- The corner of the cabin entrance is corroded



### Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.  
- With tire chains  
- Articulated-hinge : Play & Loose



### Note for Engine



Admin. No. 3000062451

\*This report is only for your reference. We are not responsible for the actual condition of checked item.