



Inspection Report

Inspection Date: 2023/09/07

Excavators

General Information

Maker	KOMATSU		
Model Number	PC138US-2E1		
Year	2006		
Hour (h)	9363	Meter	Working
Serial Number	KMTPC043A01007541		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
	- Pippings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	Oil leak	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		855		

Note for External Appearance



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- One of the right lower rollers is broken



Engine

Model	SAA4D95LE-3
Serial Number	118982
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000051054

*This report is only for your reference. We are not responsible for the actual condition of checked item.