



# Inspection Report


Inspection Date: 2018/06/15

## Excavators


General Information			
Maker	YANMAR		
Model Number	SV08-1		
Year	2007		
Hour (h)	1909	Meter	Not Working
Serial Number	13164B		


Options	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)		380		


Note for External Appearance
The body is partly painted



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	180	180	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
Upper structure movement is unchecked


Note for Undercarriage
- The rubber shoes have deteriorated over time and are partly worn
- Traveling motion is unchecked


Engine	
Model	2TE67L-BV
Serial Number	5794
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

Note for Operating Component


Note for Engine
Engine movement is unchecked (unable to start)


Admin No. 2018060818