



Inspection Report

Inspection Date: 2017/12/05

Excavators

General Information

Maker	KATO		
Model Number	HD308USV		
Year	2012		
Hour (h)	6518	Meter	Working
Serial Number	5519		

Options

- | | |
|-------------|-------------------|
| - CAB | - Speed changer |
| - Blade | - Air conditioner |
| - Arm Crane | - Piping |
| - EPA | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		Oil oozing	No	Small
Bucket		No	No	Big
Bucket Size (mm)	650			

Note for External Appearance

The body has some dents and scratches



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

2 sides of the arm are reinforced



Note for Undercarriage

- The rubber pads are severely worn
- Some of the rubber pads are lost



Engine

Model	AU-4LE2XYSB-01	
Serial Number	4LE2-287097	
Engine Oil Leak	Oil oozing	
Engine Oil Gauge	OK	
Radiator	OK	
Exhaust Color	Normal	
Blow-by	No	
Engine Sound	OK	
Hydraulic Pump	Oil oozing	
Water Pump	No water leak	
Oil Cooler	No oil leak	
Motor	No oil leak	
Multi Lever	-	

Note for Operating Component

- Rear camera
- Oil leak from the pipes of the control levers



Note for Engine

- No air conditioner belt
- The pulley of the air conditioner belt has a play
- Oil oozing from the hydraulic pump hoses
- The battery is flat



Lot No ARA012-0004 Admin No. 2017110827