



Inspection Report

Inspection Date: 2021/06/21

Excavators

General Information

Maker	CAT		
Model Number	313DCR		
Year	2011		
Hour (h)	4829	Meter	Working
Serial Number	CAT0313DPLCE00432		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	- Breaker Pipings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	925			

Note for External Appearance

- The right cover is damaged



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- One of the left shoe plates is damaged



Engine

Model	C4 2
Serial Number	JKH10123
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil leak
Multi Lever	No oil leak

Note for Operating Component

- The wiper does not work



Note for Engine

- The engine hood rod does not work properly
- The oil gauge is damaged
- Engine oil is not enough



Admin No. 3000032697