



# Inspection Report

Inspection Date: 2024/05/29

## Excavators


General Information			
Maker	KOMATSU		
Model Number	PC38UU-3		
Year	2008		
Hour (h)		Meter	Working
Serial Number	KMTPC018J05010072		

Options	
- CNP	- Speed changer
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		510		

**Note for External Appearance**


- The covers have some rust and dents



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	NG	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


**Note for Upper Structure**

- The arm is cracked
- Concrete adheres to the bucket



**Note for Undercarriage**


- The idlers are worn



Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

**Note for Operating Component**

- The monitor has some problems (hour meter is submerged in water and unable to read)
- The monitor lens is cracked
- The seat is torn



**Note for Engine**



Admin No. 3000058857