



Inspection Report


Inspection Date: 2018/03/19

Excavators


General Information			
Maker	KOMATSU		
Model Number	PC78US-6N0		
Year	2005		
Hour (h)	5317	Meter	Working
Serial Number	8855		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		650		


Note for External Appearance


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
- The rubber pads have deteriorated over time and are partly worn - Oil oozing from the left reduction drive


Engine	
Model	S4D95LE-3
Serial Number	110775
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Lot No ARA013-0025 Admin No. 2018030713