



Inspection Report

Inspection Date: 2018/09/05


Excavators

General Information			
Maker	KUBOTA		
Model Number	U-15-3S		
Year			
Hour (h)	2981	Meter	Working
Serial Number	43319		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		400		

Note for External Appearance



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	230	230	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage



Engine	
Model	D782-K2A
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	Unchecked
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The roof of the canopy is partly damaged



Note for Engine



Admin No. 2018090009