



Inspection Report

Inspection Date: 2018/07/24

Truck

General Information

Maker	MITSUBISHI
Model Number	KC-FE517BD
Year	1996
Mileage (km)	149179
Serial Number	FE517BD-426909

Note for External Appearance

- 3-way dump truck
- ShinMaywa DT-38SAY

Engine

Model	4D33
Serial Number	-
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- F5
- A/C is working

Note for Engine

Admin. No. 2018070825

*This report is only for your reference. We are not responsible for the actual condition of checked item.