



Inspection Report

Inspection Date:

#N/A

General Information

Maker	KOMATSU
Model Number	CD10R-1
Year	2002
Hour (h)	1937
Serial Number	1074

Note for External Appearance

- The body has some rust and corrosion

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	Unchecked
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	Unchecked

Note for Control Panel

Note for Engine

Other Information

- Oil oozing from the dump cylinder

Admin. No. 3000087935

*This report is only for your reference. We are not responsible for the actual condition of checked item.