Inspection Report

Inspection Date: 2026/11/11

Excavators

General Information

Maker	KOMATSU		
Model Number	PC20MR-3		
Year	2018		
Hour (h)	2380	**Meter**	Working
Serial Number	KMTPC215KJE024555		

Options

- CAB	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	**Left**	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		420		

Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	**Right**
Shoe Width (mm)	250	250
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Engine

Model	3D76E-6NDA
Serial Number	13742
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for External Appearance

- Repainted
- The body has rust and scratches



Note for Upper Structure

- The bucket side cutters are missing



Note for Undercarriage



Note for Operating Component



Note for Engine



Admin No. 3000091512

*This report is only for your reference. We are not responsible for the actual condition of checked item.