



# Inspection Report

Inspection Date: 2022/07/08

## Roller

### General Information

|                      |            |
|----------------------|------------|
| <b>Maker</b>         | SAKAI      |
| <b>Model Number</b>  | TS160      |
| <b>Year</b>          | 1996       |
| <b>Hour (h)</b>      | 6108       |
| <b>Serial Number</b> | TTS5-20810 |

### Engine


|                         |               |
|-------------------------|---------------|
| <b>Model</b>            |               |
| <b>Serial Number</b>    | 224278        |
| <b>Engine Oil Leak</b>  | Oil oozing    |
| <b>Engine Oil Gauge</b> | OK            |
| <b>Exhaust Color</b>    | Normal        |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Water Pump</b>       | No water leak |
| <b>Radiator</b>         | OK            |

### Note for External Appearance

- The body is rusty



### Note for Undercarriage



### Note for Operating Component



### Note for Engine



Admin. No. 3000041090

\*This report is only for your reference. We are not responsible for the actual condition of checked item.