



# Inspection Report

Inspection Date: 2026/05/22

## Excavators

### General Information

#ERROR!	KOMATSU		
Model Number	PC38UU-5		
Year	2015		
Hour (h)	3338	Meter	Working
Serial Number	KMTPC220VFE016857		

### Options

- |              |                 |
|--------------|-----------------|
| - CNP        | - Speed changer |
| - Multilever |                 |
| - Blade      |                 |
| - Arm Crane  |                 |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		520		

### Note for External Appearance



### Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure

- No bucket side cutters



### Note for Undercarriage

- The idlers are slightly worn



### Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

### Note for Operating Component



### Note for Engine

- The battery is flat. The machine worked normally with the booster cables.



Admin No. 3000084982