



Inspection Report


Inspection Date: 2017/09/13

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-30-3S		
Year	2006		
Hour (h)	3431	Meter	Working
Serial Number	61630		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		420		


Note for External Appearance
Not original color



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
The left rubber shoe is as good as new


Engine	
Model	D1503-KA
Serial Number	600382
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component
- The seat is partly torn
- The seat has a cover


Note for Engine
The mounting location of the water tank is broken


Admin No. 2017090027