

SR-G2000 Crusher/Recycler/Screen

2019/12/26

BASIC INFORMATION

Inspection Date		Model	SR-G2000	Serial No.	106
Date of Manufacture		Hourmeter	9733 HR	Condition of Hourmeter	
Hourmeter (Estimated)		Engine No.		Job Status	General Contractor/Civil Engineering
Accident History		Type of Shoe	Grouser	Stamp	
Others					

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Traveling	Normal
Clutch		Crusher/Screen		Conveyor Device	Normal
Feeder	Normal	Console	Normal	Remote Control	Normal メンテナンス用有線リモコン

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	Yes (Right), Yes (Left)	Wear: Track Link Extension (Right)	Moderate/Within Service Limit	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread (Right)	Slight	Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins (Right)	Slight
Wear: Track Link Pins (Left)	Slight	Wear: Track Shoe/Rubber Shoe	Slight	Bent/Broken/Missing: Track Shoe	No
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Wear/Deformation: Tooth/Cutters	Wear: Moderate/Within Service Limit, Deformation: Moderate	Wear/Deformation: Screen		Wear/Deformation: Jaw Crusher	
Crusher V belt		Wear/Deformation: Conveyor	Deformation: Moderate, Wear: Moderate/Within Service Limit	Wear: King Pins	

OIL/WATER/AIR LEAK

Aux. Cylinder (Right)	No	Aux. Cylinder (Left)	No	Oil Leak: Engine	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	
Oil Leak: Center Joint		Oil Leak: Crusher Device		Oil Leak: Conveyor Motor	No
Oil Leak: Crushing Motor		Oil Leak: Pump Device	No		

APPEARANCE

Main frame	Good Condition	Track Frame	Good Condition	Hopper	Deformed/Dent
Side Covers	Deformed/Dent, Rusted/Corroded				

INTERIOR

Console	Faded				
---------	-------	--	--	--	--

OVERALL RATING

Appearance Evaluation	Fair	Rust/Corrosion	Moderate	Overall Rating	Fair
Special Notes					