



Inspection Report

Inspection Date: 2024/03/29

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78US-8		
Year	2014		
Hour (h)	4092	Meter	Working
Serial Number	KMTPC213VEA028928		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Piping

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	640			

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The arm has been reinforced

Note for Undercarriage



Engine

Model	SAA4D95LE-5
Serial Number	559176
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

- The battery is flat; the machine worked normally with the booster cables

Admin No. 3000057352