



Inspection Report

Inspection Date:

Aerial Work Platform

General Information

Maker	HINO
Model Number	PB-XZU344M
Year	2006
Hour (h)	7089
Serial Number	XZU344-1000217

Note for External Appearance

- AICHI SK22A
- SN:695574
- YEAR: 2006
- Maximum height of the platform: 22.1m
- Tire size: 205/85R16 117/115L
- SNOW TIRE
- The track frame is rusty and corroded

Engine

Model	N04C-TB
Serial Number	
Engine Oil Leak	#N/A
Engine Oil Gauge	#N/A
Exhaust Color	#N/A
Blow-by	#N/A
Engine Sound	#N/A
Radiator	#N/A
Water Pump	#N/A
Injection Pump	#N/A

Note for Control Panel

- F5
- Mileage: 77,706km
- The storage function of the power mirror does not works well

Note for Engine

Other Information

Admin. No. 3000064959

*This report is only for your reference. We are not responsible for the actual condition of checked item.