



Inspection Report

Inspection Date:

Vibrating Roller

General Information

Maker	MEIWA
Model Number	MSR5SS
Year	
Hour (h)	379
Serial Number	A5901

Note for External Appearance

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Other Information

Admin. No. 3000057741

*This report is only for your reference. We are not responsible for the actual condition of checked item.