



# Inspection Report

Inspection Date: 2019/07/10

## Excavators

### General Information

<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK210D-9		
<b>Year</b>			
<b>Hour (h)</b>	4137	<b>Meter</b>	Working
<b>Serial Number</b>	YN13-71027		

### Options

- CAB	
- Multilever	
	- Pipings

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Unchecked
Bucket Size (mm)	1030			

### Note for External Appearance

- A standard bucket will be attached before shipment according to the seller
- The counterweight has some scratches



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure



### Note for Undercarriage



### Engine

<b>Model</b>	J05E-TJ
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	Unchecked
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 2019070557