



Inspection Report

Inspection Date: 2018/05/17

Excavators

General Information

Maker	KOBELCO		
Model Number	SK200-6E		
Year	2004		
Hour (h)	11588	Meter	Working
Serial Number	YN09-35789		

Options

- CAB	
- Multilever	
- Arm Crane	
- EPA	
- Air conditioner	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	Oil leak	No	
	Arm	No	No	No
	Bucket	No	No	Big
Bucket Size (mm)	1040			

Note for External Appearance



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

Rotation is unchecked



Note for Undercarriage

- The shoe plates are partly broken
- Traveling motion is unchecked



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- Some parts are lost
- The air conditioner does not have enough power



Note for Engine



Admin No. 2018050413