

### **Inspection Report**

Inspection Date: 2024/08/02

#### Excavators

General Information		
Maker	HITACHI	
Model Number	ZX120-3	
Year	2012	
Hour (h)	6084 Meter	Working
Serial Number	HCM1R100K00088827	

#### **Upper Structure**

		Cylinder		Play
		Oil Leak	Scratch/Rust	Flay
Boom	Left	No	No	Small
Boom	Right	No	No	oman
	Arm	Oil oozing	No	Small
	Bucket	No	No	Big
Bucket Siz	ze (mm)	885		

#### Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

# EngineModelAJ-4JJ1XYSA-03Serial Number142661Engine Oil LeakNo oil leakEngine Oil GaugeOKRadiatorOKRadiatorNormalBlow-byNoBlow-byNo oil leakHydraulic PumpNo oil leakWater PumpNo water leakOil CoolerNo oil leakMotirNo oil leakMotirNo oil leak

## Options - CAB - Speed changer - Multilever - Air conditioner - Breaker Pipings

#### Note for External Appearance



Note for Upper Structure	

Note for Undercarriage	

Note for Operating Component	
Note for Engine	



Admin No.

3000061140

\*This report is only for your reference. We are not responsible for the actual condition of checked item