



# Inspection Report

Inspection Date: 2019/02/22

## Excavators

General Information			
Maker	KUBOTA		
Model Number	U-15-3S		
Year			
Hour (h)	2106	Meter	Working
Serial Number	45446		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		400		

Note for External Appearance
The body is not the original color

Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	230	230	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

Note for Undercarriage
- The shoes are loose
- The shoe links are loose

Engine	
Model	D782-K3A
Serial Number	7S1909
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

Note for Engine
The battery is flat

Admin No. 2019020521