



Inspection Report

Inspection Date: 2022/07/09

Excavators

General Information

Maker	HITACHI		
Model Number	ZX135UR		
Year	2008		
Hour (h)	6215	Meter	Working
Serial Number	HCM1SM00V0005729		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm	No	Scratch	Small	
Bucket	No	No	Small	
Bucket Size (mm)	850			

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- Oil oozing from 4 left lower rollers and 3 right lower rollers
- Some rubber pads are missing



Engine

Model	BB-4BG1 TRG
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000041624