



Inspection Report

Inspection Date: 2024/12/24

Excavators

General Information

Maker	YANMAR		
Model Number	SV100-2A		
Year	2015		
Hour (h)	3714	Meter	Working
Serial Number	20827		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	840			

Note for External Appearance

- The body has some scratches, rust, and corrosion



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	470	470	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	NG	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

- The undercarriage is rusty and corroded



Engine

Model	4TNV98CT-VBV
Serial Number	21773
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Not enough cooling water
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000067490