



Inspection Report


Inspection Date: 2017/08/10

Excavators


General Information			
Maker	YANMAR		
Model Number	Vio40-3		
Year	2004		
Hour (h)	2894	Meter	Working
Serial Number	30602B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		570		


Note for External Appearance
Repainted


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	350	350	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
The rubber shoes have deteriorated over time, have cracks, and are worn


Engine	
Model	3TNV88-XBV
Serial Number	5386
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2017080148