# Inspection Report

Inspection Date: 2026/10/29

## Excavators

### General Information

| | | | |
|---|---|---|---|
| **Maker** | KOMATSU | | |
| **Model Number** | PC78UU-8 | | |
| **Year** | 2014 | | |
| **Hour (h)** | 5927 | **Meter** | Working |
| **Serial Number** | KMTPC213CEA027947 | | |

### Options

| | |
|---|---|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | |
| - Arm Crane | |

### Upper Structure

| | | Cylinder | | Play |
|---|---|---|---|---|
| | | Oil Leak | Scratch/Rust | |
| **Boom** | **Left** | No | No | Small |
| | **Right** | N/A | N/A | |
| **Arm** | | Oil oozing | No | Small |
| **Bucket** | | No | No | Big |
| **Bucket Size (mm)** | | 640 | | |

### Note for External Appearance

- Repainted
- The body has some scratches and rust



### Note for Upper Structure



### Undercarriage

| | | |
|---|---|---|
| **Shoe Type** | Steel shoes with rubber pads | |
| **Swing Circle** | No oil leak | |
| | **Left** | **Right** |
| **Shoe Width (mm)** | 450 | 450 |
| **Idler** | OK | OK |
| **Sprocket** | OK | OK |
| **Pin Bush** | OK | OK |
| **Upper Roller** | OK | OK |
| **Track Roller** | OK | OK |
| **Shoe Link** | OK | OK |

### Note for Undercarriage



### Engine

| | |
|---|---|
| **Model** | |
| **Serial Number** | |
| **Engine Oil Leak** | No oil leak |
| **Engine Oil Gauge** | OK |
| **Radiator** | OK |
| **Exhaust Color** | Normal |
| **Blow-by** | No |
| **Engine Sound** | OK |
| **Hydraulic Pump** | No oil leak |
| **Water Pump** | No water leak |
| **Oil Cooler** | No oil leak |
| **Motor** | No oil leak |
| **Multi Lever** | No oil leak |

### Note for Operating Component



### Note for Engine



Admin No. 3000091153

*This report is only for your reference. We are not responsible for the actual condition of checked item.