



Inspection Report

Inspection Date: 2018/12/11


Excavators

General Information			
Maker	HITACHI		
Model Number	ZX55UR-2		
Year	2008		
Hour (h)	3811	Meter	Working
Serial Number	30650		

Options	
- CNP	
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		590		

Note for External Appearance
 Arm crane movement and its switch are unchecked



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage



Engine	
Model	V2403-M-DI-EU5
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	Unchecked
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
 The seat is partly torn



Note for Engine



Admin No. 2018120062