



Inspection Report

Inspection Date: 2019/02/19


Excavators

General Information			
Maker	KOBELCO		
Model Number	SK200-8		
Year	2008		
Hour (h)	5673	Meter	Not Working
Serial Number	YN11-51406		

Options	
- CAB	- Air conditioner
- Multilever	
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	No	No	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)		1040		

Note for External Appearance




Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
Operational condition of the upper structure is unchecked




Note for Undercarriage
Traveling motion is unchecked




Engine	
Model	J08E-TI
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine
Operational condition of the engine is unchecked because the battery is flat



Admin No. 2019020325