



Inspection Report


Inspection Date: 2018/03/16

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-153S		
Year	2007		
Hour (h)	888	Meter	Replaced
Serial Number	40413		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		350		


Note for External Appearance


Undercarriage		
Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The tip of the inside of the arm has some dents


Note for Undercarriage
Width adjustable (max: 1230mm)


Engine	
Model	D782-K3A
Serial Number	7N1671
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component
Unable to use the track-width change lever (sticked)


Note for Engine


Lot No ARA013-0031 Admin No. 2018030698