



# Inspection Report

Inspection Date: 2016/09/14

## Mini Excavator

### General Information

Maker	KOMATSU
Model Number	PC28UU-3
Year	2005
Hour (h)	3656
Serial Number	320**

### Note for External Appearance

Frame dent  
Cover crack



### Upper Structure

Boom Cylinder	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	425
Swing	Backlash and play

### Note for Upper Structure

Bucket pin and arm pin and boom pin and offset pin have plays



### Operating Component

Speed Pedal	No
-------------	----

### Note for Operating Component

Torn seat



### Undercarriage

Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	290	290
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Undercarriage



### Engine

Model	3D82AE-3HB
Serial Number	18230
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil cooler

### Note for Engine



admin No

2016090257

\*This report is only for your reference. We are not responsible for the actual condition of checked item.