



Inspection Report

Inspection Date: 2022/08/31

Excavators

General Information

| | | | |
|----------------------|-------------------|--------------|---------|
| Maker | HITACHI | | |
| Model Number | ZX75US-3 | | |
| Year | 2014 | | |
| Hour (h) | 2436 | Meter | Working |
| Serial Number | HCM1P300J00066202 | | |

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | - Pipings |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|------------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | Oil oozing | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | No | No | Small |
| Bucket Size (mm) | 655 | | | |

Note for External Appearance

- The body chassis number (VIN stamp) is unchecked due to the cover
- The engine room cover won't open because the key cylinder is stiff



Note for Upper Structure

- The arm has been reinforced



Undercarriage

| | | |
|---------------------|------------------------------|--------------|
| Shoe Type | Steel shoes with rubber pads | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 450 | 450 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

Note for Undercarriage



Engine

| | |
|-------------------------|---------------|
| Model | AU-4LE2X |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | Unchecked |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Operating Component



Note for Engine

- The engine oil condition is unchecked



Admin No. 3000042433