



# Inspection Report


Inspection Date: 2018/03/14

## Excavators


General Information			
Maker	KOBELCO		
Model Number	SK30SR-5		
Year	2008		
Hour (h)	3051	Meter	Working
Serial Number	PW14-45305		


Options	
- CNP	- Pippings
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		450		


Note for External Appearance



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	NG	NG

Note for Upper Structure
- No working lamp - The arm crane hook has a play


Note for Undercarriage
- One of the right lower rollers is broken - The shoe links are slightly worn - The rubber pads are worn


Engine	
Model	3TNV88-BPYB
Serial Number	-
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

Note for Operating Component
- The mounting parts of the hour meter are lost - The hour meter is unclear - The arm crane monitor is broken


Note for Engine
The hydraulic oil tank has been welded


Lot No ARA013-0041 Admin No. 2018030503