



Inspection Report

Inspection Date: 2022/08/19

Excavators

General Information

Maker	HITACHI		
Model Number	ZX75US-3		
Year	2014		
Hour (h)	3089	Meter	Working
Serial Number	HCM1P300P00066181		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	660			

Note for External Appearance

- The body is rusty and damaged
 - The body chassis number (VIN stamp) is unchecked



Undercarriage

Shoe Type	Steel		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The bucket side cutters are missing



Engine


Model	4LE2XCUA
Serial Number	4LE2-621850
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Undercarriage



Note for Operating Component

- The cover of the fuse box is missing
 - The air conditioner is broken



Note for Engine



Admin No. 3000042430