



Inspection Report

Inspection Date: 2018/10/04

Generator

General Information

| | |
|----------------------|-----------|
| Maker | DENYO |
| Model Number | DCA-90ESH |
| Year | |
| Hour (h) | |
| Serial Number | 3796393 |

Note for External Appearance

Engine

| | |
|-------------------------|---------------|
| Model | J08C-P |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Radiator | OK |
| Water Pump | No water leak |
| Injection Pump | No fuel leak |

Note for Control Panel

The hour meter has been replaced (1210h+8343h)

Note for Engine

According to the seller, there are oil leak and oil oozing from the body while operating

Admin. No. 2018100017

*This report is only for your reference. We are not responsible for the actual condition of checked item.