



# Inspection Report

Inspection Date: 2024/03/06

## Wheel Loader

### General Information

<b>Maker</b>	KUBOTA
<b>Model Number</b>	R430E
<b>Year</b>	2018
<b>Hour (h)</b>	38
<b>Serial Number</b>	JKUR4305H00H10448

### Note for External Appearance



### Upper Structure

<b>Lift Arm Cylinder (Left)</b>	No oil leak
<b>Lift Arm Cylinder (Right)</b>	No oil leak
<b>Bucket Cylinder (Left)</b>	No oil leak
<b>Bucket Cylinder (Right)</b>	No oil leak

### Note for Upper Structure



### Undercarriage

<b>Front Accel</b>	No oil leak
<b>Rear Accel</b>	No oil leak

### Note for Operating Component

- CAB (cabin)
- Air conditioner



### Engine

<b>Model</b>	
<b>Serial Number</b>	7JT4504
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for Undercarriage



### Documents

<b>Automobile Inspection Certificate</b>	No
--	----

### Note for Engine



Admin. No. 3000055782

\*This report is only for your reference. We are not responsible for the actual condition of checked item.